Buckingham Branch Railroad Bulletin Delivery

Railroad	Richmond & Alleghany Division		January 31, 2018		
Number	996	Issued			
То	TRACK&STRUCTURES				
Bulletins	137				
OK	03:50	Dispatcher	JJL		
Voided At		Ву			

Buckingham Branch Railroad Richmond & Alleghany Division Current Operating Bulletin 137

Effective at 15:45 January 30, 2018

Timetable Number: 2

General Order(s) in Effect: 11

edmont Void	Item	Form	Limits	Speed	From - Until	Foreman	Flag	F.Int DATE
Void	Item	1 01111	LITTIES	(MPH)	110III - Ollul	i Oreman	i iag	Condition
	1	С	MP 101 - MP 108	Poor walking	g condtions both side	s of tracks ties di	stributed	09/20/17
	2	Α	MP 106.6 - MP 106.8	10F			YES	06/02/17
	3	С	MP 112 - MP 114	CSX bulletins issued for BB local trains will have the following train IDs: (Z710=Z710) (Z631=Z631) (Z628=Z373) (Z629=Z609) (Z626=Z371) (Z799=Z807).				11/28/17
	4	Α	MP 128.2 - MP 128.3	10F			YES	01/23/18
	5	С	MP 145.14	Be on the lo	okout for increased tr	affic due to loggi	ng operation.	12/20/17
	6	С	MP 152.6	Be on the lo operation.	okout for increased tr	uck traffic due to	logging	08/10/17
	7	С	MP 157.16	Be on the lo	okout for increased tr	affic due to loggi	ng operation.	01/03/18
ange Sı	ubdivis	ion (CT	C)					
	8			No Restric	tions			
rth Mou	ıntain S	Subdivi	sion (CTC)					
Void	Item	Form	Limits	Speed (MPH)	From - Until	Foreman	Flag	F.Int DATE Condition
	9	С	MP 180.1 - MP 183.1	between MF	The locomotive horn 180.1 and MP 183.1 and mp 183.1			11/30/17
	10	С	MP 193.89		w a temporary(6 mont 9. DOT# 967955B	hs or more) priva	te crossing	10/04/16
	4.4	0	MD 104.6		mant stared in Craza			00/10/17

			require sounding of the horn.	3	
10	С	MP 193.89	There is now a temporary(6 months or more) private crossing at MP 193.89. DOT# 967955B		10/04/16
11	С	MP 194.6	Track equipment stored in Crozet spur track		08/10/17
12	Α	MP 204.8 - MP 205	25F 30P	YES	03/24/17
13	Α	MP 207.7 - MP 207.9	25F 30P	YES	07/10/17
14	С	MP 208.1	Walkway on Northside of Track OOS		02/17/16
15	С	MP 219.7	Equipment stored at the end of Staunton Industry Track.		12/21/17
16	С	MP 222.1	At Factory, track OOS inside the gate.		10/04/17
17	С	MP 234.2 - MP 240.6	Poor walking conditions on both sides of main ties.	ing conditions on both sides of main track due to	
18	Α	MP 241.8 - MP 242	50P	NO	09/21/17
19	Α	MP 255.5 - MP 256.3	55P	NO	09/22/17
20	С	MP 267	Crane Spur track new portable derail installed		01/30/18

END OF Current Operating Bulletin 137 January 30, 2018
TOTAL OF 20 ITEMS